


Styli, Stems and Holders

Optional Accessories for Dial Test Indicators

Styli (for Metric Models Only*)

* Except for universal type dial test indicator (513-304G).

- Stylus length affects the scale factor of an indicator. The styli provided as standard give a scale factor of unity.



ø0.5mm ball-point



190547 (L=14.7mm)
190549 (L=20.9mm)
190654 (L=22.3mm)
190656 (L=44.5mm)

ø0.7mm ball-point



190548 (L=14.7mm)
190550 (L=20.9mm)
190653 (L=22.3mm)
190655 (L=44.5mm)

ø1mm ball-point (Carbide)



21CZA044 (L=12.8mm)
103017 (L=14.7mm)
103013 (L=20.9mm)
137558 (L=22.3mm)
137746 (L=36.8mm)
136235 (L=44.5mm)

ø2mm ball-point (Carbide)



21CZA036 (L=12.8mm)
103010 (L=14.7mm)
103006 (L=20.9mm)
137557 (L=22.3mm)
129949 (L=36.8mm)
136013 (L=44.5mm)

ø2mm ball-point (Ruby)



21CZA212 (L=12.8mm)
21CZA209 (L=14.7mm)
21CZA201 (L=20.9mm)
21CZA210 (L=22.3mm)
21CZA211 (L=44.5mm)

ø3mm ball-point (Carbide)



21CZA045 (L=12.8mm)
103018 (L=14.7mm)
103014 (L=20.9mm)
137559 (L=22.3mm)
137747 (L=36.8mm)
136236 (L=44.5mm)

Spanner



102037

Stems with Knurled Clamp Ring

ø4mm (.157" DIA.)



902802

ø8mm



902804

3/8" DIA.



902805

Swivel Clamps

- Can be used with Holding Bars.

For ø4mm stem, ø8mm stem, and dovetail



900321

For .157" DIA. stem, 3/8" DIA. stem, and dovetail



900322

Holding Bars



9 x 9mm

953638 (Length: 50mm)
900209 (Length: 100mm)



ø8mm (.315" DIA)

900211 (Length: 115mm/ 4.528")



.25" x .5"


953639 (Length: 2")
900306 (Length: 4")

Universal Holder

- Allows the indicator to be set at the desired attitude to the workpiece.



901916 (ø8mm stem)
901459 (.25" DIA. stem)
901461 (ø6mm stem)




Centering Holder

- Allows large diameter cylinders or holes to be centered on a machine tool.



901959 (ø8mm stem)
901997 (.25" DIA. stem)




Styli, Stems and Holders

Optional Accessories for Pocket Type Dial Test Indicators

Styli (for Metric Models Only)

- Stylus length affects the scale factor of an indicator. The styli provided as standard give a scale factor of unity.



ø0.5mm ball-point



190547 (L=14.7mm)
190549 (L=20.9mm)
190656 (L=44.5mm)

ø0.7mm ball-point



190548 (L=14.7mm)
190550 (L=20.9mm)
190655 (L=44.5mm)

ø1mm ball-point (Carbide)



136756 (L=12.1mm)
103017 (L=14.7mm)
103013 (L=20.9mm)
137746 (L=36.8mm)
136235 (L=44.5mm)

ø2mm ball-point (Carbide)



136104 (L=12.1mm)
103010 (L=14.7mm)
103006 (L=20.9mm)
129949 (L=36.8mm)
136013 (L=44.5mm)

ø2mm ball-point (Ruby)



21CZA209 (L=14.7mm)
21CZA201 (L=20.9mm)
21CZA211 (L=44.5mm)

ø3mm ball-point (Carbide)



136758 (L=12.1mm)
103018 (L=14.7mm)
103014 (L=20.9mm)
137747 (L=36.8mm)
136236 (L=44.5mm)

Stems

ø4mm (.157" DIA.)



102389

ø8mm



102822

3/8" DIA.



102081

Swivel Clamps

- Can be used with Holding Bars.

For ø4mm stem
and ø8mm stem, and
dovetail



900321

For .157" DIA. stem and
3/8" DIA. stem, and
dovetail



900322

Holding Bars



9 x 9mm

953638 (Length: 50mm)
900209 (Length: 100mm)



ø8mm (.315" DIA.)

900211 (Length: 115mm)



.25" x .5"

953639 (Length: 2")
900306 (Length: 4")

Spanner



301336

Universal Holder

- Allows the indicator to be set at the desired attitude to the workpiece.



901917 (ø8mm stem)
901546 (.25" DIA. stem)
901547 (ø6mm stem)

